

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,835,490 B1
APPLICATION NO. : 09/937652
DATED : December 28, 2004
INVENTOR(S) : Okada et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

column 20, line 62, as follows:

“ $V_{(a-b)}M_2Ti_{(41-4a+b)}Cr_{(59-6a-b-c)}M_c$ ” should be -- $V_{(a-d)}M_2dTi_{(41-0.4a+b)}Cr_{(59-0.6a-b-c)}M_c$ --;

and column 21, line 2, as follows:

“Mo, Nb, Ta, W, Mn, Fe and Al” should be -- Mo, Nb, Ta, W, Fe and Al --;

and column 21, line 34, as follows:

“ $V_{(a-b)}M_2Ti_{(41-0.4a+b)}Cr_{(59-0.6a-b-c)}M_c$ ” should be -- $V_{(a-d)}M_2dTi_{(41-0.4a+b)}Cr_{(59-0.6a-b-c)}M_c$ --;

and column 21, line 41, as follows:

“from the group consisting of Mo, Nb, Ta, W, Mn, Fe” should be -- from the group consisting of Mo, Nb, Ta, W, Fe --;

and column 21, line 49, as follows:

“group consisting of Nb, Mo, Ta, W, Mn, Fe, al, B, C,” should be -- group consisting of Nb, Mo, Ta, W, Mn, Fe, Al, B, C, --;

and column 22, line 49, as follows:

“ $V_{(a-b)}M_2dTi_{(41-0.4a+b)}Cr_{(59-0.6a-b-c)}M_c$ ” should be -- $V_{(a-d)}M_2dTi_{(41-0.4a+b)}Cr_{(59-0.6a-b-c)}M_c$ --;

and column 22, line 56, as follows:


“group consisting of Mo, Nb, Ta, W, Mn, Fe and Al.” should be -- group consisting of Mo, Nb, Ta, W, Fe and Al. --;

and column 24, line 27, as follows:

“group consisting of Mo, Nb, Ta, W, Mn, Fe and Al” should be -- group consisting of Mo, Nb, Ta, W, Fe and Al --;

Signed and Sealed this

Fourth Day of May, 2010



David J. Kappos
Director of the United States Patent and Trademark Office

and column 24, line 49, as follows:

“wherein $0 \leq a \leq 70$ at %, $-10 \leq b \leq 10 + c$, $d \leq a$, M is at” should be -- wherein
 $0 \leq a \leq 70$ at %, $-10 \leq b \leq 10 + c$, $0 \leq c$, $0 \leq d \leq a$, M is at --.